

Patiala Aviation Club

Civil Aerodrome, Sangrur Road, Patiala – 147001 (Pb)

Email: patialaaviationclub@gmail.com, Tele – 0175-2307069

REQUIREMENT OF SPARE PART FOR CESSNA 172 R AIRCRAFT

S.No.	PART NO.	Description	QTY Required
1	6404-1 X (565-548-041)	Mixture Control	2
2	6403	Throttle Control	2
3	AN6-23A	Bolt (MBQ-10)	20
4	NAS1149F0763P	Washer (MBQ-100)	200
5	AN6-27A	Bolt (MBQ-5)	10
6	AN7-44A	Bolt	4
7	AN7-45A	Bolt	4
8	MS21045L6	Nut (MBQ-25)	50
9	J2218-61	Washer	8
10	NAS1149F0763P	Washer (MBQ-100)	200
11	MS21045L7	Nut (MBQ-10)	20
12	AE6695H0180-180	Hose Assy.	2
13	83278	Sensor Oil Pressure	2
14	AE3663161H0184	Hose Assy.	2
15	AE3663163E0240	Hose Assy.	2
16	AE3663161G0164	Hose Assy.	2
17	MS21045L3	Nut (MBQ-25)	50
18	S3461-108	Bolt	4
19	F222000	Duct (MBQ-12Ft)	24
20	J7444-42	Mount Cowl	16
21	S2269-1	Clamp	2
22	STD761	Pin (MBQ-10)	20
23	J-23502-1	Shock Mount Kit	2
24	AA3215CC	vacuum Pump	2
25	9910591-7	Alternator (New) *(core charges \$ 850/-)	1
26	149-NL/EC	Starter	2

Note:

1. Sealed bids must reach to Manager, Patiala Aviation Club, Civil Aerodrome, Sangrur Road, Patiala – 147001 by February 02, 2019 upto 5:00 pm.

2. Rates, taxes, freight, custom duty, insurance, government levies or core charges must be separately mentioned in the bid.
3. Payment detail, delivery date and availability of items must be clearly mentioned in the quotation.
4. All prices of quoted items should be in USD.
5. Delay in delivery of items may attract penalty as decided by the authority.

(Manager)