

Patiala Aviation Club
Civil Aerodrome, Sangrur Road, Patiala - 147 001 (Pb)
E mail: patialaaviationclub@gmail.com, Tele - 0175 - 2307069

Requirement of Engine spares for installation of new engine IO360L2A
for Cessna 172S and Other spares.

S/N	Description	Part Number	Quantity Required
1	Mixture Control	6404-1X(565-548-041)	1
2	Throttle control	6403	1
3	Bolt	AN 6-23A	MBQ
4	Washer	NAS1149F0763P	MBQ
5	Bolt	AN6-27A	MBQ
6	Bolt	AN7-44A	2
7	Bolt	AN7-45A	2
8	Nut	MS21045L6	MBQ
9	Washer	J2218-61	4
10	Nut	MS21045L7	10
11	Hose assy.	AE6695H0180-180	1
12	Oil Pressure Switch	83278	1
13	Hose Assy	AE3663161H0184	1
14	Hose Assy	AE3663163E0240	1
15	Hose assy	AE3663161G0164	1
16	Nut	MS21045L3	2
17	Bolt	S3461-108	2
18	Duct	F222000	12FT
19	Mount cowl	J7444-42	8
20	Clamp	S2269-1	1
21	Pin	STD761	10
22	Shock mount kit	J-23502-1	2
23	Vaccum pump	AA3215CC	1
24	Alternator	9910591-7	1
25	Starter	149-NL/EC	1
26	Coupling kit	82-06768	1
27	Oil Filter	CH48110-1	40
28	Main tire	156E6681	10
29	Bolt Kit	B4622-43	2
30	Nut	MS20365-1032C	50
31	Bolt	An3-5	50
32	O-ring	M83248/1-011	20
33	Gasket	0756041-1	50
34	O-ring	M83248/1-138	25
35	O-ring	M83248/1-011	25
36	Hose Carb Heat	S1053K24 , 17.0In long	4
37	Hose Carb heat	S1053K16T, 17.0In long	4

Note:-

- 1** Sealed bids must reach to Manger, Patiala Aviation Club, Civil Aerodrome, Sangrur Road, Patiala - 147001 by November 15, 2019 by 5:00pm.
- 2** Rates, taxes, freight, custom duty, insurance, government levies or core charges must be separately mentioned in the bid.
- 3** Payment details, delivery date and availability of items must be clearly mentioned in the quotation.
- 4** All prices of quoted items should be in USD.
- 5** Delay in delivery of items may attract penalty as decided by authority.

Sd/-
(Aircraft Maintenance Engineer)